

Fig. 1




Fig. 2





Fig. 3



*Fig. 4*




Fig. 5







Fig. 6



*Fig. 7*




*Fig. 8*



CONTACT BETWEEN THE GROOVE OF THE  
HOUSING AND THE OUTER ROLLER AT THE  
OPPOSITE SIDE OF THE LOADED SIDE



*Fig. 9*





*Fig. 11*






Fig. 12



*Fig. 13*



*Fig. 14*




Fig. 15






Fig. 16






*Fig. 17*



*Fig. 18*



*Fig. 19*

